CEMP AUDIT SITE INSPECTION

Reference Number	OXAD-C2566-C-HBC-WB-CEMP-Q4-004	Rev: 0	**Project**	Harrow School– Abu Dhabi
Date	8th October 2026		**Contractor**	M/s. Al Hikma Building Contracting LLC

Audited By	Yumaima Naeem	**Role**	Environmental Specialist

Weather	
Condition	Sunny
Temperature °C	45°C

Inspections Notes:

An Environmental Joint Inspection has been carried out at Construction of Harrow School– Abu Dhabi Project on Thursday 8th October 2026 in line with the Project approved CEMP and Proactive Monitoring Programme of 2026

(Al Suweidi, HBC & Oxygen) representatives were present during the Environmental Audit Program.

The visit was limited to the Stores, Waste Segregation Area, Active work zones & Site offices.

The following observations have been highlighted by M/s OXYGEN CONSULTANCY LIMITED (Environmental Specialist) and accordingly appropriate actions shall be taken by all involved parties in line with response category and across the whole project.

Code	Findings (high/Risk/Low)
A	Environmental Non-conformances – (Immediate action) - High Risk
B	Medium Environmental nonconformity (Immediate action) - Medium Risk
C	Minor Environmental Incidents - (Immediate action) - Low Risk

Findings:

Sl. No.	Findings	Findings Code	Evidence Photographs (If Available)
1	**During the CEMP audit, it was observed that diesel cans were over stacked within the drip trays in the chemical store, resulting in inadequate secondary containment. Adequate drip trays shall be provided to ensure proper containment of all diesel cans.** **The required storage temperature was also not maintained; suitable cooling shall be provided to maintain appropriate storage conditions. Proper housekeeping and material management shall be maintained within the chemical store.**	A	 

			

2	**Waste accumulation was observed in the designated waste storage areas. Proper waste segregation shall be maintained, and waste shall be removed regularly to prevent accumulation and maintain good housekeeping.**	A	 

3	**Waterproofing material drums were observed exposed to direct sunlight. The drums shall be stored in a designated covered area under suitable temperature conditions.**	B	
4	**Soil contamination was observed due to diesel spillage around the generator drip tray. The spilled diesel shall be cleaned immediately, and the drip tray shall be emptied and maintained to prevent further contamination.**	A	 

Issued By (Environmental Consultant): M/s OXYGEN CONSULTANCY LIMITED		
Name: Yumaima Naeem		8/10/2026