



تقرير خدمة
Service Report

17/09/2022	تاريخ Date	2100508	الرقم المرجعي Reference number
305	رقم الوحدة Unit number	2266	رقم المبنى Building number
#	Description		
	DB breaker inside the unit replaced.		
	corridor pin bulbs replaced.		
	Bedroom wall cabinet door hinges replaced.		
	Small bathroom mirror light and wall light pull set replaced.		

Tenant Feedback Survey استبيان آراء المستأجرين

Please Rate the below, Base on the Performance of the Maintenance Team		Satisfy (Yes)	Not- Satisfy (No)
1	Technician Performance; (Did the technician attend with Politeness & Friendliness attitude?)		
2	Overall Performance (Did we comply overall performance applied)		
توقيع الساكن / حارس البناية Signature: Tenant or Watchman		توقيع الفني Technician Signature	توقيع المهندس المسؤول Engineer In charge signature
 0554857060			
We, as a contractor, reiterate you to ensure that our services are delivered in concurrence with measurement criteria.			