شركة الحكمة لمقاولات البناء (ذ.م.م)
Al Hikma Building Contracting (L.L.C.)


LOGISTICS DEPARTMENT

HBC VEHICLE RELEASING FORM

Date	10/9/2026
Plate No.	85176
Description	Nissan Sentra
KM Reading (Before)	
KM Reading (After)	

Body Damage Report

Receiving Condition **Returning Condition**



Notes: _____

Accessories Checklist:	**Receiving**	**Returning**
1. Registration Card	☑	☐
2. Fuel Card	☑	☐
3. Spare Tyre / Wheel	☑	☐
4. Wipers	☐	☐
5. Floor Mats	☐	☐
6. Antenna	☐	☐
7. Reflective Warning Triangle	☑	☐
8. Fire Extinguisher	☐	☐
9. Tools	☐	☐
10. Jack	☑	☐

Notes: _____



Fuel Level – Upon Receiving



Fuel Level – Returning

Wheels Condition Checklist:	**Receiving**	**Returning**
11. Front Right Side	☑ Good ☐ Bad	☐ Good ☐ Bad
12. Front Left Side	☑ Good ☐ Bad	☐ Good ☐ Bad
13. Rear Right Side	☑ Good ☐ Bad	☐ Good ☐ Bad
14. Rear Left Side	☑ Good ☐ Bad	☐ Good ☐ Bad

Notes: _____

Notes: _____

Receiving Details		**Returning Details**	
Over-All Condition		**Over-All Condition**	
Name	MANHAL	**Name**	
Contact No.	0569791501	**Contact No.**	
Date	10/9/2026	**Date**	
Time	4:30 PM	**Time**	
Signature		**Signature**	