



تقرير خدمة Service Report			
12 / 08 / 2022	تاريخ Date	2040474	الرقم المرجعي Reference number
801	رقم الوحدة Unit number	P/332	رقم المبنى Building number
#	Description		
1	Replaced main door cylinder and safety chain.		
2	Replaced 6 nos corridor light bulbs and telephone box cylinder.		
3	Replaced living room door cylinder.		
4	Replaced bedroom 1 door cylinder.		
5	Replaced bedroom 2 door cylinder.		
6	Replaced kitchen door cylinder, 2 nos sink stoppers, and 4 nos tube lights.		
7	Replaced medium bathroom shower tray RAK and washbasin water stopper.		
8	Replaced big bathroom down light.		
9	Deep cleaning in the whole flat completed.		
10	Full painting in the whole flat completed.		
NOTE: Empty flat, no available tenant and WM refused to sign as it is tenant responsibility.			
استبيان آراء المستأجرين Tenant Feedback Survey			
Please Rate the below, Base on the Performance of the Maintenance Team		Satisfy (Yes)	Not- Satisfy (No)
1	Technician Performance; (Did the technician attend with Politeness & Friendliness attitude?)		
2	Overall Performance (Did we comply overall performance applied)		
توقيع الساكن / حارس البناية Signature: Tenant or Watchman		توقيع الفني Technician Signature	توقيع المهندس المسؤول Engineer In charge signature



We, as a contractor, reiterate you to ensure that our services are delivered in concurrence with measurement criteria.

Al Jeel Valley
General Maintenance